

**To:** Lloyd, Lisa[Lloyd.Lisa@epa.gov]  
**From:** Karen Dickson  
**Sent:** Thur 8/13/2015 10:14:40 PM  
**Subject:** FW: Gold King ICS230-OS

**From:** Bruce Holloman - CDPS [mailto:[bruce.holloman@state.co.us](mailto:bruce.holloman@state.co.us)]  
**Sent:** Thursday, August 13, 2015 4:15 PM  
**To:** Karen Dickson  
**Subject:** Re: Gold King ICS230-OS

Thank you Karen. I do not have those IAP documents electronically.

Bruce E Holloman

Colorado Department of Public Safety

Office of Emergency Management

720-884-6053

On Aug 13, 2015, at 12:06, Karen Dickson <[KDickson@co.montezuma.co.us](mailto:KDickson@co.montezuma.co.us)> wrote:

Bruce,

Attached is a combined, revised schedule for the Gold King Mine Blowout. There are a couple of tentative meetings that I was not able to confirm yet in a timely manner. Please review and contact me with any questions.

Also, please let me know if you received the August 13<sup>th</sup> –August 15<sup>th</sup> IAP.

Karen Dickson

Southwest Incident Management Team

Deputy Planning Section Chief

970-739-7880

--

<Gold King ICS230-OS.doc>

--